

# QUICK START GUIDE

## 9300-USBE - USB TO ETHERNET ADAPTOR

### KIT CONTENTS



CD



USBE



USB Cable



Ethernet Cable




Crossover Ethernet Cable



Cable Bag

## Connections



### **A** To Begin Install:

Insert the USB cable into the adapter, then plug it into an open USB port on the computer. Place the CD into the computer's CD disc drive.



## B New Hardware Wizard



## C RSLinx



## D



Power —  
 100BaseT Speed —  
 10BaseT Speed —  
 Ethernet Activity —

**Note:**  
 Units MAC ID  
 located on label

For more information go to: [www.rockwellautomation.com](http://www.rockwellautomation.com)