


## Powr-Polish™ Flexible Abrasive

- Fine-grain, non-dusting abrasive held together by a flexible bond
- Serves as both commutator cleaner and burnisher
- Removes dirt and grease—imparts super-finished surface
- Non-conductive and non-loading



Sizes (Inches)	Cat. No.
3/8 x 1/2 x 5	<b>82-001</b>
3/8 x 3/4 x 5	<b>82-002</b>
5/8 x 1 x 5	<b>82-003</b>
1 x 2 x 5	<b>82-004</b>
1 x 4 x 5	<b>82-005</b>
1/8 x 1 x 5	<b>82-006</b>

Please allow 2-3 weeks for delivery.

## Commutator Smoothie® Resurfacing Tool



- Designed to smooth commutators of auto generators, starting motors and other similar equipment
- 8-1/2 in. plastic handle with a 5/16 in. x 7/8 in. x 11/16 in. resurfacer on each end
- Features one polish-grade and one finish-grade resurfacer
- Bent handle reaches into any motor frame
- Non-conductive for user safety

Description	Cat. No.
Commutator Smoothie® Resurfacing Tool	<b>80-033</b>

Please allow 2-3 weeks for delivery.

## Brush Seater and Commutator Cleaner



- Gentle acting abrasive for seating carbon brushes and cleaning commutators and slip rings
- Soft, loosely bound grain produces a scouring effect when held against commutator
- Will not remove or scratch copper
- Self-cleaning
- Available in soft(S), medium(M) and hard(H) grades

Sizes (Inches)	Grades	Cat. No.
1/4 x 1/4 x 4-3/4	M, H	<b>23-001*</b>
1/2 x 1/4 x 4-3/4	M, H	<b>23-002*</b>
3/8 x 3/8 x 4-3/4	M, H	<b>23-003*</b>
1/2 x 3/8 x 4-3/4	S, M, H	<b>23-004*</b>
1/2 x 1/2 x 4-3/4	S, M, H	<b>23-005*</b>
5/8 x 1/2 x 4-3/4	S, M, H	<b>23-006*</b>
3/4 x 1/2 x 4-3/4	S, M, H	<b>23-007*</b>
1-1/8 x 5/8 x 4-3/4	S, M, H	<b>23-008*</b>
1/2 x 1 x 4-3/4	S, M, H	<b>23-027*</b>
1 x 1 x 4-3/4	—	<b>23-035S</b>
2 x 1 x 4-3/4	—	<b>23-036S</b>
3 x 2 x 4	—	<b>23-039S</b>
3 x 2 x 6	—	<b>23-041S</b>
3 x 2 x 8	—	<b>23-042S</b>

\*Add grade letter suffix to Cat. No.

Please allow 2-3 weeks for delivery.