

## Broan S97012038 Ventilation Fan Motor and Blower W



### Product Highlights

- Genuine Broan S97012038 motor and blower wheel assembly
- This motor has an original part number of S99080216 and works with the following Broan ventilation fan models: 659, 662, 663A, 663B, 663C
- 663D, 663E, 668, 688, 678, 678B, 688, 688A, 688B, 688C, 688D, 688E
- This motor is the exact replacement for the following motor numbers: 15617, 162502, 02S0055, 0340775B, 101-1770, 14266A, 15194A, 301-3001
- 5KSB33BG1858, C202A, CC0053, CC0154, P-10294, P-14266A, P14266A, P-15194, P-15617, P-608-31-1, P-9983, S10625002, S10625236, S10625237, S20625002