



11625 Prosperous Drive  
Odessa, Florida 33556  
PH: 877-584-5847  
FAX: 727- 376-6956

To: Whom it may concern

From: Luke Hill

**Subject: IT3/0 Wire Range Marking**

Date: August 3, 2009

Total number of pages:1

---

Polaris Connectors was recently forced to revamp the marking process on all insulated connectors due to a new requirement by Underwriter Laboratories. This change forced us to manufacture new stamp tooling for all insulated connectors. Unfortunately, during this process an error was made resulting in an incorrect wire range marking for the IT3/0. These parts were inadvertently marked with a wire range of 250MCM - #6AWG as opposed to the appropriate 3/0 - #6 AWG between October 1<sup>st</sup>, 2008, to July 17<sup>th</sup> 2009. We have recently recalled all mismarked IT3/0's to be remarked with the correct wire range. We apologize for any inconvenience this may have caused.

If you have any questions regarding this error please don't hesitate to contact us.

Regards,  
Luke Hill  
Engineering Manager  
Polaris Electrical Connectors